

Shell Mill Cutter

- Suggested starting point for cutting 4140 or 6150.
- Speed Rate 500 RPM
- Feed Rate 20 I.P.M.
- Depth of cut .100”

