

LSM-R-200 4 & 5

- Suggested spindle speed 800 R.P.M.
- Feed rate 12 I.P.M.
- Insert RP12
- Cut diameter 2.00”
- Cutter heights of 1.50”

